



Whitby Harbour LOCAL NOTICE TO MARINERS

Harbours, Docks and Piers Clauses Act 1847

Whitby Harbour West Pier Fog Signal Inoperable

All Mariners are advised that Whitby Harbour Fog Signal located at the Harbour Entrance is inoperable.

Mariners are advised to exercise extreme caution when navigating in the area until repairs can be implemented.

Repairs will be carried out as soon as possible.

Further advice can be obtained from Whitby LPS on VHF Channel 11 or Whitby Harbour Office.

James Buck
Deputy Harbour Master